

3D SENSOR IN ELECTRONIC PEDOMETER



POWER WALKER

Model No. PW-610 / 611



You **need not** attach pedometer on your **waist** anymore

Just put in your **Pocket!!**



FUNCTIONS



STEP COUNTER

Counts the Number of Steps taken while walking or jogging up to 99999 steps.



DISTANCE

Measures the Distance covered while walking or jogging from 0.00 km or 0.00 mile to 999.99 km or 999.99 miles. (km:PW-610 / mile:PW-611)



CALORIE

Measures the Number of Calorie burned while walking or jogging from 0.00 to 9999.9 kcal.



ACTIVITY TIME

Measures the Time covered while walking or jogging from 0H 00M to 23H 59M.



SPEED

Measures the Speed covered while walking or jogging from 0.0 meter/minute or 0.0 mph to 999.9 meter/minute or 999.9 mph. (meter/minute:PW-610 / mph:PW-611)



CLOCK

24 hours system clock.



7DAYS MEMORY

The Records of Number of Steps and Consumption Calorie are automatically stored every day up to 7 days ago.



POWER WALKING

The PW sensor measures Number of Steps and calculate Burned Fat Weight in case of high pitch aerobics walking (Power Walking Mode). (g:PW-610 / oz.:PW-611)



DUAL DISPLAY

Wide and Easy to ready LCD shows your walking record and data.



3D SENSOR

3 directions accelerometer (3D) sensor is mounted and monitor every steps you take.